



Any fabrication procedure or technique not contained within the Wilsonart® Solid Surface Fabrication Manual will not be recognized by Wilsonart, LLC as an approved method of fabrication. Deviations from these techniques must be approved in writing by a Wilsonart Representative.



## General Safety:

Safety is a critical concern for any shop and key to a successful business. The following safety rules should be incorporated into your safety program to help prevent an accident. Safety training, knowledge, product use and environment are the responsibility of the facility owner and the shop employees.

**CAUTION: Always follow product, equipment and/or tool manufacturer's recommendations and instructions carefully.**

- Read directions carefully before fabricating/installing Wilsonart® Solid Surface.
- Read and follow the instruction manual before operating the different tools.
- Keep all guards in place and in working order.
- Ensure all tools are properly grounded. Never remove the third prong.
- Keep work area clean, uncluttered and well lit.
- Don't use electric power tools in a damp or wet work area.
- Keep visitors at a safe distance from the work area.
- Use the right tools. Don't force a tool or attachment to do a job it was not designed to perform.
- Always use safety glasses or approved eye protection and/or face shield, ear/noise protectors and safety shoes. (FIG. 4A & 4B)
- Wear the proper apparel, no loose clothing or jewelry.
- Secure all work with the proper clamp or vise to a stable work surface.
- Don't overreach. Keep proper footing and balance at all times.
- Maintain tools in top condition. Disconnect tools before servicing and when changing accessories such as blades, bits, cutters, etc.
- Keep and use denatured alcohol, adhesives and materials in a safe, ventilated place.
- Dust collection should be used when cutting, routing and sanding. Tools should be used with dust collection at all times.



Figure 4A



Figure 4B

## Wilsonart® Hard Surface Adhesive:

- Wilsonart® Hard Surface Adhesive is for professional use only. Always follow the manufacturer's recommendations and instructions carefully. (FIG. 5A)
- Warning: This seam kit contains the following hazardous ingredients: Methyl Methacrylate, Benzoyl Peroxide, and Dibutyl Pathlate. Avoid prolonged breathing of vapors. Use only in a well ventilated area. Keep out of reach of children. Eye protection is always recommended. Motors and other equipment used in the fabrication and installation process must be UL labeled explosion proof.
- For further information refer to Wilsonart® Hard Surface Adhesive Material Safety Data Sheet available on request. Contact your local distributor or call 1-800-433-3222 for immediate response.




Figure 5A

### FAB TIP:

- For Wilsonart Solid Surface hard seam design color chart, refer to [www.wilsonart.com](http://www.wilsonart.com)

# INTRODUCTION

---

- Wipe all sanding dust from countertop surface between grit changes. Inspect finish for consistency after each sanding step to aide in final finish.
- Darker colors will require more attention to obtain the desired final finish.(Semi-Gloss or Gloss)
- Be careful when selling dark colors and/or semi- gloss or gloss finishes. Inform your customer of the possible extra care necessary to maintain a dark color and/or finishes higher than a standard
- Matte or Satin finish. Care and Maintenance or may need professional to maintain finish.
- Use both horizontal and vertical strokes and overlapping your strokes by at least 50% for a consistent finish.
- Scratches will be more visible.
- Avoid high traffic areas if possible.
- Take extra care when fabricating and handling to avoid scratches to reduce unnecessary sanding.